

SPEED DATA ANALYSIS

Location



Latitude: 42.579687 Longitude: -70.744872

Analysis Time Period



Start 3/24/2021 3:50 PM End 3/31/2021 3:50 PM

Vehicles Analyzed



2,175

Total Enforceable Violations



1

% Enforceable Violations



0%

Enforcement Rating

LOW



Speed Limit



25

Enforcement Tolerance



10

Average Speed



23

85th Percentile Speed



27



Speed Enforcement Evaluator

Location

Pole3, Hickory Hill Rd March 24 to March 31

GPS

Latitude: 42.579687 Longitude: -70.744872

Analysis Dates

Start: 3/24/2021 End: 3/31/2021

Equipment Used

JAMAR Law Enforcement Data Radar

Installed By

Lt. Mark McCoy

Requested By

Chief Todd Fitzgerald


ADT

318


Total Percentage of Enforceable Violations

Posted Speed Limit 25 MPH Enforcement Tolerance 10 MPH

Enforcement Limit Greater than 35 MPH



Percent Speeding: 0% Rating: Low





Vehicle:	Totals -	 Combined
----------	----------	------------------------------

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	0	17	40	157	434	681	612	279	69	9	1	1

85th Percentile: 26.9

V۵	hic	۔ ما	Tota	le _	N	lorth.	1
VC	11110		ı Ula	13 -	ıv	IUI III.	- 1

	<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
ĺ	0	0	0	13	34	108	292	399	254	56	6	2	0	0
	85th Perc	entile: 24	.9											

Vehicle Totals - South, 2

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	0	4	6	49	142	282	358	223	63	7	1	1
5th Perce	entile: 27 (a											

85th Percentile: 27.9



