



## SPEED DATA ANALYSIS

### Location



Pipeline Rd (Upper Pine Street  
near Water Treatment Plant  
Latitude: 0.000000  
Longitude: 0.000000

### Analysis Time Period



Start	End
6/17/2022 9:20 AM	7/6/2022 10:08 AM

### Vehicles Analyzed



3,803

### Speed Limit



25

### Total Enforceable Violations



5

### Enforcement Tolerance



10

### % Enforceable Violations



0%

### Average Speed



18

### Enforcement Rating

LOW

### 85th Percentile Speed



23



## Speed Enforcement Evaluator

### Location

Pipeline Rd (Upper Pine Street)

### Closest Cross Street

near Water Treatment Plant

### GPS

Latitude: 0.000000  
Longitude: 0.000000

### Analysis Dates

Start: 6/17/2022  
End: 7/6/2022

### Equipment Used

JAMAR Law Enforcement Data Radar

### Installed By


Lt. Mark McCoy

### Requested By

DPW Chuck Dam

### Total Percentage of Enforceable Violations

Posted Speed Limit 25 MPH  
Enforcement Tolerance 10 MPH  
Enforcement Limit Greater than 35 MPH



**Manchester-by-the-Sea Police Department**  
**10 Central Street**  
**Manchester-by-the-Sea, MA 01944**



**Vehicle Totals - Combined**

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	53	323	714	896	850	566	248	119	25	6	4	1
85th Percentile: 22.9													

**Vehicle Totals - North, 1**

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	49	189	330	456	408	253	96	44	9	3	2	1
85th Percentile: 22.9													

**Vehicle Totals - South, 2**

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	4	134	384	440	442	313	152	75	16	3	2	0
85th Percentile: 23.9													

